

Dr. -Ing. Giok Djien Go
Pfahlgrabenstr. 45
D-65510 Idstein
Germany



phone/fax +49 6126 8949

IFW

Registered

Mrs. Arleon Graham, please excuse me when I wrongly wrote your name
Supervisory Legal Instruments Examiner (Tel. 3008 3233)
USPTO

10/690,740 ✓ "Shoulder-belt-portion guiding assembly"; Confirmation no. 6752
Notice of Non-Compliant Amendment dated 02/24/2005
Docket No: G6A1

Dear Mrs. Graham,

According to USPTO's flyer Rev. 3 (07/24/03) added and deleted text must be shown by underlining and strikethrough. Why has USPTO changed this new procedure *again* into the old one, underlining and but double bracket? How can I know it?

Thank you for your help and attention in advance.

Kind regards

Go

Pp. 14/line 2 "comes into contact with [[to]]" in (E3) is amended into "comes into contact with" in (E3A).
Pp. 13/line 3 "deflector 5 [[or]] single movable, head-rest tube 5" is amended into "deflector 5, suited for
a single movable, head-rest tube 5."

Claim 2 in lines 14 and 25 is corrected from [[the height of the head]] to a height of a head.
Claims 1, 2, 6 to 13, 16 are amended.
Claims 13, 14 are replaced.

Attached.

21-page substitute application in double space (300305)
6-page marked-up Claims of 10/690,740 (300305)

Dr.-Ing. Giok Djien Go
Pfahlgrabenstr. 45
D-65510 Idstein
Germany

USPTO-G6A1//05.04.2005